



EP306

Product name
Earth Positive® Bomber Jacket Hoodie

Fibre composition / Yarn type
100% GOTS Organic Cotton Compact Spun

Fabric type / Weight
Brushed Fleece 3-ply 8.9 oz/yd² 300 g/m²

Commodity code Origin
6110 2091 00 India

Available sizes
XS S M L XL 2XL


Certifications

Available colours

Black
BL

Dark Navy
NA

Light
Heather
LHE



Size spec

Size	Width (A)		Length (B)	
	cm	inch	cm	inch
XS	61	24	59.5	23½
S	64	25¼	62.5	24½
M	67	26½	64.5	25½
L	70	27½	66.5	26¼
XL	73	28¾	68.5	27
2XL	76	30	69.5	27½



Discharge printing suitability

Important: This guide serves as a general reference, and results may vary. We strongly recommend testing prior to production.

Core colours				Solid colours								
		Very Good	Moderate	Not Suitable			Very Good	Moderate	Not Suitable			
	Black BL	✓				Dark Navy NA	✓					
					Light Heather LHE			✓				

Printing Guide

Print type	Print type	Printing suitability 0 = Not Suitable, 1 = Poor, 2 = Moderate, 3 = Good, 4 = Very Good, 5 = Excellent	Printing recommendations
Fleece 100% Organic Cotton solid colours (excluding RFD & Sueded colours)	Screen print	★★★★★	Follow manufacturer's recommendations for printing and curing settings.
	Discharge	★★★★★	The results may vary from one colour to another. Refer to our discharge printing recommendations on the following page.
	Transfer (Sticker)	★★★★☆	Follow manufacturer's recommendations for curing settings.
	Direct to garment	★★★★★	Follow manufacturer's recommendations for printing and curing settings.
	Embroidery	★★★★★	Direct embroidery, stitched patch, labels

***Maximum heat recommendation for back neck label** Fusing 180°C / 3-6 sec, 6 psi
Curing 180°C / 1 min

Print type	Print type	Printing suitability 0 = Not Suitable, 1 = Poor, 2 = Moderate, 3 = Good, 4 = Very Good, 5 = Excellent	Printing recommendations
Fleece 100% Organic Cotton Heather Colours	Screen print	★★★★★	Follow manufacturer's recommendations for printing and curing settings.
	Discharge	★★★★☆	The results may vary from one colour to another. Refer to our discharge printing recommendations on the following page.
	Transfer (Sticker)	★★★★☆	Follow manufacturer's recommendations for curing settings.
	Direct to garment	★★★★☆	Follow manufacturer's recommendations for printing and curing settings.
	Embroidery	★★★★★	Direct embroidery, stitched patch, labels

***Maximum heat recommendation for back neck label** Fusing 180°C / 3-6 sec, 6 psi
Curing 180°C / 1 min